ACS-USA Instruction






Image of adapter ACS-USA





Holes 1 are used for mounting the bracket of HT001C.
Holes 2 are used for mounting the bracket of HT003C/HT005C/HT006C.
Holes 3 are used for mounting the bracket of HT008C.
Hole 4 is used for mounting HT029C.

Holes 5 are used for mounting on a thin niche. Holes 7 are used for mounting on a deep niche.


I. Mounting with HT001C lights










II. Mounting with HT003C/HT005C/HT006C lights










III. Mounting with HT008C lights









IV. Mounting with HT029C lights






V. Mounting with HT009C lights







Dimensions

